

Special Note for Internal Battery Option B3

How to maximize operating time and battery life

Maximizing Battery Run Time:

The run time from the internal battery can be maximized by starting a charging process immediately before using the unit on battery power. There are 3 ways to do this:

- 1) Cycle the power switch ON then OFF
- 2) Disconnect and reconnect the DC power plug at the rear of the unit
- 3) Disconnect and reconnect the DC power adaptor on the mains side.

A full charge of an empty battery can take up to 6 hours. More information on battery operation can be found in section 6 of the User Manual.

Maximizing Battery Life Time:

- 1) The battery will reach its best performance after the first few charge-discharge cycles.
- 2) Always use the external power adaptor supplied with the APSIN3000 for normal operation and charging. This will make sure that the charging circuits work as specified.
- 3) Fully charge the APSIN3000 after running it from the battery.
- 4) If an APSIN3000 with internal battery will be stored for an extended period of time, fully charge it before storage, then remove the power adaptor and make sure that the power switch is in the OFF position. After long-term storage, first charge the unit for 4-6 hours.